



Intertek Recall News: Jewellery with 2.8% lead content, made in China, recalled in Sweden


From: Intertek全國公證 Taiwan
Sent: Friday, January 10, 2020 1:41 PM
To: The LEAD Group Inc
Subject: Intertek全國公證 消費性產品召回(Recall)通報



Dec 2019

消費性產品召回(Recall)通報

2019/11/30~2019/12/31期間，消費品召回案例包含珠寶、紋身墨水、玩具及化妝品，節錄如下：

類別	產品照片	通報國	原產國	召回原因	違反法規
珠寶		瑞典	中國	金屬含有0.27%的鎘及2.8%的鉛	REACH



全國公證檢驗股份有限公司

11492台北市內湖區瑞光路 423號 8樓

www.intertek-twn.com

Translation of the Chinese ring (see photo above) recall notice, by Dr Hugh Xin Xi Zhu, for The LEAD Group Inc, Australia

The first item (above) in Intertek's Recall News: Jewelry/Jewellery contains 2.8% Lead, which exceeds the legal level [see REACH Regulation No 836/2012 extracts in the following article]. It was sold in Sweden. The product was made China. It has been notified to the public and recalled in Sweden.
